


Bogdan-Secian




4864500Y



649500X

650250X



430

490

240

360

150

320

FIG 6s



Administratia Fluviala a Dunarii de Jos - Galati, Romania
S.C.N. Giurgiu - Biroul Hidrotehnic, Harta Electronica



Sondaj de control Dunarea Fluviala, efectuat de nava Donaris 3

Zona Bogdan-Secian Km 783+000 - Km 786+000

Adancimi efective
Mira ref. Calafat

-48 cm

EV	IV	C	IR	ER
2.6	2.7	2.8	2.4	2.3

Scara 1:5000

LATIME MIN. 150m/km 783.6

Data: 27.11.2018