


- < 1.00
- 1.00 - 1.24
- 1.25 - 1.49
- 1.50 - 1.74
- 1.75 - 1.99
- 2.00 - 2.24
- 2.25 - 2.49
- 2.50 - 2.74
- 2.75 - 2.99
- 3.00 - 3.24
- 3.25 - 3.49
- 3.50 - 3.74
- 3.75 - 3.99
- 4.00 - 4.24
- 4.25 - 4.49
- 4.50 - 4.74
- 4.75 - 4.99
- 5.00 - 5.24
- 5.25 - 5.49
- >= 5.50



F2-P.O.8.5.1-07

ROMÂNIA Ministerul Transporturilor Administrația Fluvială a Dunării de Jos R.A.- Galați Agenția Căi Navigabile Brăila				
Sondaj efectuat de: NT Semnal 3				
Zona:	Carcaliu km25-km26	Proiect:	Sondaj de control	Adancimi minime efective EV 3.4 CE 3.3 ER 2.3
Mira de referinta:	Braila	Observatii:		
Cota mira:	+97 cm	Brat Macin:		
Data sondajului:	05.12.2018			
Scara:	1:5000			
Sistem de coord.:	UTM-35N	Latime minima senal:	60	